Removal of KURS-A Hardware from Progress M1-10 ● Firing of ОДУ Pyro Valves ● Pressurization of Prop & Oxidizer Tanks in Progress Prop Resupply System

GMT	Crew	Activity
06:00–06:10		Morning inspection
06:10-06:40		Post-sleep
06:40-07:30		BREAKFAST
07:30-08:00	FE-1	Prep for work
07:30–07:55	CDR	
07:55–08:00		PLANTS-2: payload status check
08:00–08:15		Daily planning conference (S-band)
08:15–11:15		Removal of KURS-A hardware from Progress M1-10
11:15–11:45	CDR	Disinfection of A-P/P-P hoses prior to Progress/SM water transfer
11:15–11:25	FE-1	Increment 7 daily payload status
11:30–12:45	- '	Physical exercise (TVIS)
11:45–12:45	CDR	Physical exercise (VELO + Load Trainer-1 / day 3)
12:45–13:45		LUNCH
13:45–14:45	FE-1	NGL installation for tests
13:45–14:15	CDR	CMO skill training
14:15–14:35		IMS tagup (S-band)
14:35–15:05		Water transfer from Progress RODNIK to SM RODNIK (hardware config and initiation of transfer)
14:45–15:15	FE-1	CMO skill training
15:05–15:35	CDR	Maintenance of СОЖ
15:15–15:30	FE-1	Food questionnaire
15:30–15:50		Transfer of TVIS/RED files to MEC
15:35–16:15	CDR	IMS file prep
15:50–16:10	FE-1	Transfer of HRM file to MEC
16:10–16:25		HRM file erase
16:15–17:45	CDR	Physical exercise (TVIS-3)
16:25–16:55	FE-1	Restart of all PCS computers (once a week)
16:55–18:10		Physical exercise (RED)
18:10–18:20		CWC audit
18:20–18:40		Daily plan review
18:40–18:55		Daily planning conference (S-band)
18:55–19:05		Daily plan review
19:05–19:30		FD/ISS crew conference (S-band)
19:30–20:00		DINNER
20:00–20:30		Daily food prep
20:30–21:30	FE-1	Pre-sleep
20:30–21:05	CDR	Pre-sleep

21:05–21:15	Water transfer from Progress RODNIK to SM RODNIK (closeout ops without hardware deconfig)	t
21:15–21:30	Pre-sleep	
21:30-06:00	SLEEP	

NOTE: See OSTP for references to US procedures

End of radiogram